

City of Detroit  
Department of Recreation Performance Audit  
Exhibit 7 – Pittsburgh

**Overall Evaluation – Very Good Condition**

- Center entrances were clean, bright and well kept.
- Gymnasiums were nicely painted with shiny, clean floors.
- Overall inside appearance of the centers were bright and cheerful.
- Restrooms were clean with stall doors hung.
- Activity rooms such as weight-lifting and dance rooms were clean and well-lit.



Ormsby Recreation Center entrance which was clean and well kept.

City of Detroit  
Department of Recreation Performance Audit  
Exhibit 7 – Pittsburgh



The entrance to Magee Center was clean and bright.



Southside Marketplace Gymnasium with nicely painted walls and a clean, shiny floor.